Assembly Instruction | XLR Cable Connector

ORDER OF ASSEMBLY



NXT5MA



NXT5FA




Put chuck onto the cable.



Insert wires into the terminals and solder them.



Slide chuck to the insert.



Prepare the cable as shown (measurements in millimeters)



Slide insert and chuck together into the housing.



Slide the bushing onto the cable.



Finish installation: Turning bushing onto the connector.





EnovaNxt