Assembly Instruction | XLR Cable Connector

ORDER OF ASSEMBLY



NXT4MA



NXT4FA



Put chuck onto the cable.



Insert wires into the terminals
and solder them.



Slide chuck to the insert.



Prepare the cable as shown
(measurements in millimeters)



Slide insert and chuck together
into the housing.



Slide the bushing onto the cable.



Finish installation: Turning bushing
onto the connector.





EnovaNxt